

ME266

Digital Clamp Meter DT266



- The clamp multimeter will not be easily destroyed by overload test for overload protection, and the meter will auto power off after 10 mins's no operation to save energy
- Ampere-multimeter device for professional home use
Pocket size ampere tester
- Autoranging clamp multimeter can be used to measure AC and DC Voltage, AC Current, Resistance, Diode test, Data Hold, Max Value Hold. troubleshoot electrical problems safely.
- If you have basic knowledge about multimeters you can try this small multimeter for basic continuity checks and voltage measurements and also can be used for heavy ampere measurement in heavy load wires
- Salient features: AC 1000 Amp. Clamp Meter 750 Volt & DC 1000 Volt Resistance & Continuity Buzzer 2000 Count Display & Jaw Size 50 mm Data Hold & Manual Range Selection 1 X 9V. Battery